

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_RD1500_01_s _ 2013_9				
Comment Code					
Inspector Comment					
RD 1500 has their O&M Manual.					

No Photos

LM Start		Rating **	A	Issue No.	55
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_RD1500_01_s _ 2013_55				
Comment Code					
Inspector Comment					
RD 1500 maintains a stockpile of flood response material.					

No Photos

LM Start		Rating **	A	Issue No.	61
LM End		Issue Type +	Ma	Location *	N/A
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_RD1500_01_s _ 2013_61				
Comment Code					
Inspector Comment					
RD 1500 is current with it's flood response plans and training.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	0.19	Rating **	M	Issue No.	93
LM End	0.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.761730 °	38.761730 °	
			-121.677953 °	-121.677953 °	
DWR ID	DWR_RD1500_01_s_2019_93				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
There are multiple rodent holes near the landside toe.					

No Photos

LM Start	0.21	Rating **	M	Issue No.	129
LM End	0.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.761957 °	38.761957 °	
			-121.678145 °	-121.678145 °	
DWR ID	DWR_RD1500_01_f_2019_129				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Large rodent hole near the landside toe.					

No Photos

LM Start	0.32	Rating **	M	Issue No.	90
LM End	0.32	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.763334 °	38.763334 °	
			-121.679119 °	-121.679119 °	
DWR ID	DWR_RD1500_01_s_2019_90				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
A large rodent hole is near the landside shoulder.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	0.37	Rating **	M	Issue No.	128
LM End	0.38	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.763826 °	38.763909 °	
			-121.679790 °	-121.679930 °	
DWR ID	DWR_RD1500_01_f_2019_128				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Multiple rodent holes on the landside slope.					

No Photos

LM Start	0.41	Rating **	M	Issue No.	148
LM End	0.41	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.764156 °	38.764156 °	
			-121.680462 °	-121.680462 °	
DWR ID	DWR_RD1500_01_s_2020_148				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the landside slope.					

No Photos

LM Start	1.13	Rating **	M	Issue No.	127
LM End	1.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.767761 °	38.767761 °	
			-121.691900 °	-121.691900 °	
DWR ID	DWR_RD1500_01_f_2019_127				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the landside slope.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	1.17	Rating **	M	Issue No.	126
LM End	1.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.768288 °	38.768288 °
				-121.692203 °	-121.692203 °
DWR ID	DWR_RD1500_01_f_2019_126				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the landside slope.					

No Photos

LM Start	1.25	Rating **	M	Issue No.	99
LM End	1.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.769274 °	38.769274 °
				-121.691700 °	-121.691700 °
DWR ID	DWR_RD1500_01_f_2017_99				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
There are multiple rodent holes and mounds on the landside slope.					

Photo 1 of 2 : SP_2020_RD1500_189_99_20200228_00039.jpg



View of rodent holes. Spring 2018

LM Start	1.25	Rating **	M	Issue No.	99 (cont)
LM End	1.25	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2020_RD1500_189_99_20200228_00040.jpg



View of holes and mounds on landside slope. Fall 2017.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	1.25	Rating **	M	Issue No.	147
LM End	1.28	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.769342 °	38.769641 °	
			-121.691663 °	-121.691194 °	
DWR ID	DWR_RD1500_01_s _ 2020_147				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	1.25	Rating **	M	Issue No.	146
LM End	1.28	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.769343 °	38.769640 °	
			-121.691663 °	-121.691194 °	
DWR ID	DWR_RD1500_01_s _ 2020_146				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

*** Location**
 LS : Land Side N/A : Not Applicable
 WS : Water Side
 CR : Crown

**** Rating**
 A : Acceptable N : Not Inspected/Rated
 M : Minimally Acceptable C : Corrected
 U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
 Ma : Maintenance Deficiency
 Ob : Design & System Obsolescence
 En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	1.34	Rating **	A/W	Issue No.	85
LM End	1.95	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.770390 °	38.777282 °
				-121.690553 °	-121.685841 °
DWR ID	DWR_RD1500_01_f_2018_85				

Comment Code

Inspector Comment

2017 Site ID: SAC 86.3 L
Status: Eroding
2017 Field Notes: No observed change..
Site History: 2006 - New erosion upstream, new bank failures near levee but still fairly wide berm in most places. 2008 - Large berm, questionable as to if it should remain in the inventory. 2010 - Minor new erosion, old cobble starting to fail. 2011 - Cobble continues to unravel and additional slumping. 2012 - Minor new erosion at bank mid point. 2013 - Minor new erosion. 2016 - Toe relatively stable. Upper slope is over steepened.

Photo 1 of 1 : SP_2020_RD1500_189_85_20200228_00033.jpg



USACE 2013 Photo #1

LM Start	2.30	Rating **	A/W	Issue No.	87
LM End	2.52	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.781962 °	38.784936 °
				-121.688033 °	-121.690033 °
DWR ID	DWR_RD1500_01 f _ 2018_87				

Comment Code

Inspector Comment

2017 Site ID: SAC 87.1 L
Status: Eroding
2017 Field Notes: Large whole bank failure section in middle of site.
Site History: 2010 - The upstream end of the repair site at 87.0. Repair did not extend far enough upstream. 2011 - New erosion pockets. 2012 - Minor new erosion at toe. 2013 - Minor new erosion. 2015 - Significant new toe erosion. 2016 - Fresh erosion on riverbank.

Photo 1 of 1 : SP_2020_RD1500_189_87_20200228_00034.jpg



USACE 2013 Photo #1

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	2.65	Rating **	M	Issue No.	143
LM End	2.65	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		38.786129 °	38.786129 °	
			-121.687329 °	-121.687329 °	
DWR ID	DWR_RD1500_01_s _ 2020_143				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Ruts on the landside slope.					

No Photos

LM Start	2.65	Rating **	M	Issue No.	141
LM End	2.98	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.786130 °	38.789834 °	
			-121.687329 °	-121.684823 °	
DWR ID	DWR_RD1500_01_s _ 2020_141				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	2.65	Rating **	M	Issue No.	142
LM End	2.98	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.786130 °	38.789834 °	
			-121.687329 °	-121.684823 °	
DWR ID	DWR_RD1500_01_s _ 2020_142				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	3.26	Rating **	M	Issue No.	124
LM End	3.26	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.792004 °	38.792004 °
				-121.688571 °	-121.688571 °
DWR ID	DWR_RD1500_01_f_2019_124				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the landside slope.					

No Photos

LM Start	5.19	Rating **	M	Issue No.	139
LM End	5.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.802344 °	38.802344 °
				-121.712940 °	-121.712940 °
DWR ID	DWR_RD1500_01_s_2020_139				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff erosion on the landside slope.					

Photo 1 of 1 : SP_2020_RD1500_189_139_20200319_00204.jpg



View of the erosion on the landside slope. Spring 2020.

LM Start	6.24	Rating **	A/W	Issue No.	136
LM End	6.24	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.811093 °	38.811093 °
				-121.722790 °	-121.722790 °
DWR ID	DWR_RD1500_01_f_2018_136				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					
There is minor runoff on the waterside slope. Recommend monitoring.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	9.71	Rating **	A/W	Issue No.	162
LM End	9.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.853564 °	38.853564 °
				-121.725379 °	-121.725379 °
DWR ID	DWR_RD1500_01_s_2017_162				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
The area is heavily accessed by trailer residents and fishermen. Recommend monitoring.					

Photo 1 of 1 : SP_2020_RD1500_189_162_20200228_00059.jpg



View of slope stability on waterside slope. Spring 2017.

LM Start	10.19	Rating **	M	Issue No.	104
LM End	10.19	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.858839 °	38.858839 °
				-121.728650 °	-121.728650 °
DWR ID	DWR_RD1500_01_f_2019_104				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes on the landside slope.					

No Photos

LM Start	10.25	Rating **	M	Issue No.	115
LM End	10.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.859585 °	38.859585 °
				-121.729188 °	-121.729188 °
DWR ID	DWR_RD1500_01_f_2018_115				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
There are active rodent holes at the landside toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	11.64	Rating **	C	Issue No.	97
LM End	11.64	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Slope Stability			38.871281 °	38.871281 °
				-121.747215 °	-121.747215 °
DWR ID	DWR_RD1500_01_f_2019_97				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Ruts on the landside slope.					

No Photos

LM Start	11.80	Rating **	A/W	Issue No.	88
LM End	12.26	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.871848 °	38.869139 °
				-121.749349 °	-121.757108 °
DWR ID	DWR_RD1500_01_f_2018_88				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 95.8 L					
Status: Eroding					
2017 Field Notes: Sites 95.8 and 96.2 combined.					
Site History: 1997 - No toe on the large upstream rubble (mix of broken concrete, bricks, rock, and steal) - should be replaced. Oversized bank. 2001 - New slump at the downstream end. 2003 - Some minor bank retreat at the downstream end. 2004 - Some new retreat at the downstream end. 2006 - Some new erosion, mainly on the steep slope and scarps. (Pumping station is not part of the erosion site.) 2010 - Minor new erosion. 2011 - Minor new erosion at the toe. 2015 - Fresh slumping					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	12.01	Rating **	M	Issue No.	116	
LM End	12.01	Issue Type +	Ma	Location *	LS	
Category	Earthen Levee			GPS Latitude/Longitude		
				Start		End
Item	Erosion / Bank Caving			38.870730 °		38.870730 °
				-121.752908 °		-121.752908 °
DWR ID	DWR_RD1500_01_s_2017_116					
Comment Code						
E2 : Schedule repair of erosion site prior to the next inspection.						
Inspector Comment						
There is runoff erosion on the landside levee slope.						

Photo 1 of 1 : SP_2020_RD1500_189_116_20200228_00046.jpg



View of erosion on landside slope. Spring 2017.

LM Start	12.57	Rating **	M	Issue No.	118
LM End	12.57	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.867108 °	38.867108 °
				-121.761498 °	-121.761498 °
DWR ID	DWR_RD1500_01_f_2015_118				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Recommend backfilling erosion.					

No Photos

LM Start	13.98	Rating **	A/W	Issue No.	89
LM End	14.28	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.857239 °	38.861899 °
				-121.783771 °	-121.784057 °
DWR ID	DWR_RD1500_01_f_2018_89				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 99.0 L					
Status: Eroding					
2017 Field Notes: Rock continues to unravel.					
Site History: 1997 - Intermittent toe failure of the hand placed riprap; failure of toe materials.					

Photo 1 of 1 : SP_2020_RD1500_189_89_20200228_00035.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	14.17	Rating **	M	Issue No.	91
LM End	14.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Erosion / Bank Caving		38.860281 °	38.860281 °	
			-121.783247 °	-121.783247 °	
DWR ID	DWR_RD1500_01_f_2019_91				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff on the landside slope.					

No Photos

LM Start	14.23	Rating **	A/W	Issue No.	86
LM End	14.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.861112 °	38.861112 °	
			-121.783490 °	-121.783490 °	
DWR ID	DWR_RD1500_01_f_2019_86				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent hole on the landside slope.					

No Photos

LM Start	18.20	Rating **	A/W	Issue No.	79
LM End	18.20	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.899570 °	38.899570 °	
			-121.802229 °	-121.802229 °	
DWR ID	DWR_RD1500_01_f_2019_79				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes near the landside toe. Recommend monitoring.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	18.38	Rating **	A/W	Issue No.	80
LM End	19.06	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.901337 °	38.902721 °
				-121.801175 °	-121.790677 °
DWR ID	DWR_RD1500_01_f_2018_80				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 104.0 L					
Status: Eroding					
2017 Field Notes: Bank slope is relatively stable.					
Site History: 1997 - Pocket failures of cobble revetment toe; scallops of rock loss along the bank; irregular bankline developing. 2001 - Small scallops in the toe of the berm. 2005 - Still multiple erosion pockets in the toe. 2006 - Two new small slumps. 2011 - Old cobble continue to fail causing minor slumping. 2012 - Portions of site appears to be stabilizing. 2016- Cobble revetment continues to fail.					

Photo 1 of 1 : SP_2020_RD1500_189_80_20200228_00029.jpg



USACE 2013 Photo #1

LM Start	19.16	Rating **	A/W	Issue No.	81
LM End	19.47	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.904041 °	38.906697 °
				-121.790298 °	-121.792796 °
DWR ID	DWR_RD1500_01_f_2018_81				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 104.5 L					
Status: Eroding					
2017 Field Notes: Site appears stable.					
Site History: 1997 - Cobbles eroded off the clay materials; not much evidence of erosion on the toe; cobble loss on the toe. 2011 - Some minor new erosion.					

Photo 1 of 1 : SP_2020_RD1500_189_81_20200228_00030.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	23.65	Rating **	M	Issue No.	112
LM End	23.65	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			38.930239 °	38.930239 °
				-121.834972 °	-121.834972 °
DWR ID	DWR_RD1500_01_s_2018_112				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
Runoff on the waterside slope.					

No Photos

LM Start	23.69	Rating **	C	Issue No.	75
LM End	23.69	Issue Type +	Ma	Location *	CR
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Crown Surface / Depressions / Rutting			38.930802 °	38.930802 °
				-121.834822 °	-121.834822 °
DWR ID	DWR_RD1500_01_f_2019_75				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					
Fill tire ruts on the crown.					

No Photos

LM Start	24.50	Rating **	M	Issue No.	76
LM End	24.50	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.940769 °	38.940769 °
				-121.830856 °	-121.830856 °
DWR ID	DWR_RD1500_01_f_2019_76				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	24.57	Rating **	M	Issue No.	102
LM End	24.57	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.941361 °	38.941361 °	
			-121.831899 °	-121.831899 °	
DWR ID	DWR_RD1500_01_f_2018_102				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
There are rodent holes at the landside toe.					

No Photos

LM Start	25.04	Rating **	A/W	Issue No.	77
LM End	25.04	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.946748 °	38.946748 °	
			-121.835708 °	-121.835708 °	
DWR ID	DWR_RD1500_01_f_2019_77				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent hole on the landside slope.					

No Photos

LM Start	25.07	Rating **	C	Issue No.	78
LM End	25.07	Issue Type +	Ma	Location *	CR
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Crown Surface / Depressions / Rutting		38.947188 °	38.947188 °	
			-121.835656 °	-121.835656 °	
DWR ID	DWR_RD1500_01_f_2019_78				
Comment Code					
C2 : Repair depressions or ruts in the crown or slope.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	25.56	Rating **	M	Issue No.	95
LM End	25.75	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.953874 °	38.956092 °
				-121.838111 °	-121.836520 °
DWR ID	DWR_RD1500_01_s_2020_95				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	28.23	Rating **	M	Issue No.	92
LM End	28.23	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.983221 °	38.983221 °
				-121.819895 °	-121.819895 °
DWR ID	DWR_RD1500_01_f_2018_92				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent holes are located at the landside toe.					

Photo 1 of 1 : SP_2020_RD1500_189_92_20200228_00036.jpg



View of rodent holes on the landside slope. Fall 2018.

LM Start	28.30	Rating **	M	Issue No.	135
LM End	28.30	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.984158 °	38.984158 °
				-121.819868 °	-121.819868 °
DWR ID	DWR_RD1500_01_s_2019_135				
Comment Code					
A1 : Exterminate rodents and backfill and compact or grout burrows.					
Inspector Comment					
Active rodent holes are at the landside toe.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	30.60	Rating **	A/W	Issue No.	82
LM End	30.75	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			38.999745 °	39.001413 °
				-121.800898 °	-121.802889 °
DWR ID	DWR_RD1500_01_f_2018_82				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 116.0 L					
Status: Eroding					
2017 Field Notes: Minor new erosion throughout the site.					
Site History: 2000 - Eroding, vertical berm slope over a vertical cohesive toe; slow erosion but getting close to the toe. 2002 - Erosion is getting close to the levee, still eroding with some new small slumps. 2004 - Some minor new erosion. 2006 - Some new erosion, cleaned off older scars and slump faces. 2008 - New, small, partial rotational failure. 2011 - Some new minor erosion. 2016 - Fresh erosion on lower bank.					

Photo 1 of 1 : SP_2020_RD1500_189_82_20200228_00031.jpg



USACE 2013 Photo #1

LM Start	30.94	Rating **	A/W	Issue No.	83
LM End	31.60	Issue Type +	Ma	Location *	WS
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	2017 USACE Erosion Survey			39.003301 °	39.006072 °
				-121.805024 °	-121.815926 °
DWR ID	DWR_RD1500_01_f_2018_83				
Comment Code					
Inspector Comment					
2017 Site ID: SAC 116.5 L					
Status: Eroding					
2017 Field Notes: pipe and pump encroachment. site has been stable for a few years.					
Site History: 2003 - New sedimentation and some new small toe scallops at the upstream end; downstream end has some new erosion.					
2004 - Some new erosion at the toe and upper bank and some small new rotational failures (mainly minor, except at the downstream end).					
2007 - Some new slumps. 2009 - Some new scallops and site was extended upstream. 2010 - New deposition along upstream end of site, however there is also new erosion throughout the site. Site seems to be worsening, and eroding fast. Large habitat for bank swallows. 2011 - Some new minor erosion. 2012 - Minor new erosion. 2016 - Fresh erosion on lower bank.					

Photo 1 of 1 : SP_2020_RD1500_189_83_20200228_00032.jpg



USACE 2013 Photo #1

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	31.21	Rating **	M	Issue No.	105
LM End	31.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		39.005559 °	39.005559 °	
			-121.809039 °	-121.809039 °	
DWR ID	DWR_RD1500_01_s _ 2020_105				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Vehicle ruts on the landside slope.					

No Photos

LM Start	31.58	Rating **	M	Issue No.	121
LM End	31.58	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Slope Stability		39.006558 °	39.006558 °	
			-121.815694 °	-121.815694 °	
DWR ID	DWR_RD1500_01_s _ 2020_121				
Comment Code					
S3 : Repair the levee slope damaged by vehicle traffic and prevent access where possible.					
Inspector Comment					
Vehicle ruts on the waterside slope.					

No Photos

LM Start	31.79	Rating **	M	Issue No.	122
LM End	31.83	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		39.007007 °	39.007344 °	
			-121.819433 °	-121.820003 °	
DWR ID	DWR_RD1500_01_s _ 2020_122				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Sacramento River	Left	33.15	03/17/2020 03/18/2020	Zach Jojola

LM Start	32.98	Rating **	M	Issue No.	144
LM End	32.98	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.020782 °	39.020782 °
				-121.820275 °	-121.820275 °
DWR ID	DWR_RD1500_01_s_2017_144				
Comment Code					
E2 : Schedule repair of erosion site prior to the next inspection.					
Inspector Comment					
There is runoff erosion on the landside slope.					

Photo 1 of 1 : SP_2020_RD1500_189_144_20200228_00057.jpg



View of erosion on landside slope. Spring 2017.

LM Start	32.98	Rating **	M	Issue No.	107
LM End	32.98	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			39.020874 °	39.020874 °
				-121.820266 °	-121.820266 °
DWR ID	DWR_RD1500_01_f _ 2016_107				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD1500_189_107_20200228_00041.jpg



View of rodent burrows on landside slope. Fall 2016.

LM Start	32.99	Rating **	A/W	Issue No.	106
LM End	32.99	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Erosion / Bank Caving			39.021016 °	39.021016 °
				-121.820261 °	-121.820261 °
DWR ID	DWR_RD1500_01_f_2016_106				
Comment Code					
E1 : Note and monitor erosion site.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
---------------------------------------------------------------------------------------	--	-----------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------	--	------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	0.02	Rating **	M	Issue No.	21
LM End	1.85	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.761318 °	38.782981 °	
			-121.674345 °	-121.655621 °	
DWR ID	DWR_RD1500_02_s_2020_21				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	0.13	Rating **	M	Issue No.	16
LM End	0.14	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Animal Control		38.762429 °	38.782564 °	
			-121.672920 °	-121.672771 °	
DWR ID	DWR_RD1500_02_f_2018_16				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
There are multiple holes on the landside slope.					

No Photos

LM Start	0.15	Rating **	M	Issue No.	22
LM End	1.85	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.762643 °	38.782981 °	
			-121.672670 °	-121.655621 °	
DWR ID	DWR_RD1500_02_s_2020_22				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.92	Rating **	A/W	Issue No.	39
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.783865 °	38.783865 °
				-121.655170 °	-121.655170 °
DWR ID	20020				
Comment Code					
Inspector Comment					
DS_ID:20020 FS_ID:28886 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: Pumping plat was working during the field visit.Hydraulic gates on outfall structure. Motorized slide gates on waterside shoulder. FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 3] 1 of 4: 72-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 35 feet below the crown. Two concrete cutoff walls. Pumps in concrete pumping plant on the landside (LS). Timber steps on the LS slope. Two service poles and anchors on the LS shoulder. Electrical control gates in a metal and concrete building on the waterside (WS) shoulder. Flap gates on the WS end. Installed by USACE in 1950. (Construction of a four compartment concrete gravity outlet conduit under the levee authorized under Permit No. 1284, 1948 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 1993. USACE Sacramento O&M Manual 129, June 1954, (Station 1227+00)]. FS Date: 1/21/2014					

LM Start	1.92	Rating **	A/W	Issue No.	39 (cont)
LM End	1.92	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2020_28886_53098.jpg



WS view: CM shed for slide gate on levee shoulder (top) and outfall structure at levee toe (bottom).

Photo 2 of 3 : UCIP_SP_2020_28886_53096.jpg



WS view: motorized slide gates in CM shed on levee shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.92	Rating **	A/W	Issue No.	39 (cont)	
LM End	1.92	Issue Type +	Ma	Location *		
Category	Supplemental			GPS Latitude/Longitude		
				Start		End
Item	DWR UCIP LMA Responsibility			38.783865 °		38.783865 °
				-121.655170 °		-121.655170 °
DWR ID	20020					

Photo 3 of 3 : UCIP_SP_2020_28886_53097.jpg



LS view: pump house at the end of levee berm.

LM Start	1.92	Rating **	A/W	Issue No.	40
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.783885 °	38.783885 °
				-121.655158 °	-121.655158 °
DWR ID	20027				

Comment Code

Inspector Comment

DS_ID:20027
FS_ID:28883
EP_NO: N/A
Repair Type: No Action Needed
Crossing Status: Found
UCIP Comments: Pumping plant was working during the field visit. Hydraulic gates on outfall structure. Motorized slide gates on waterside shoulder.
FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 3] 2 of 4: 72-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 35 feet below the crown. Two concrete cutoff walls. Pumps in concrete pumping plant on the landside (LS). Timber steps on the LS slope. Two service poles and anchors on the LS shoulder. Electrical control gates in a metal and concrete building on the waterside (WS) shoulder. Flap gates on the WS end. Installed by USACE in 1950. (Construction of a four compartment concrete gravity outlet conduit under the levee authorized under Permit No. 1284, 1948 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 1993. USACE Sacramento O&M Manual 129, June 1954, (Station 1227+00)].
FS Date: 1/21/2014

Photo 1 of 3 : UCIP_SP_2020_28883_53085.jpg



WS view: CM shed for slide gate on levee shoulder (top) and outfall structure at levee toe (bottom).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.92	Rating **	A/W	Issue No.	40 (cont)
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.783885 °	38.783885 °	
			-121.655158 °	-121.655158 °	
DWR ID	20027				

Photo 2 of 3 : UCIP_SP_2020_28883_53083.jpg



WS view: motorized slide gates in CM shed on levee shoulder.

LM Start	1.92	Rating **	A/W	Issue No.	40 (cont)
LM End	1.92	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2020_28883_53084.jpg



LS view: pump house at the end of levee berm.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.92	Rating **	A/W	Issue No.	41
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.783904 °	38.783904 °
				-121.655149 °	-121.655149 °
DWR ID	20028				
Comment Code					
Inspector Comment					
DS_ID:20028 FS_ID:28884 EP_NO: N/A Repair Type: No Action Needed Crossing Status: Found UCIP Comments: Pumping plat was working during the field visit.Hydraulic gates on outfall structure. Motorized slide gates on waterside shoulder. FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 3] 3 of 4: 72-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 35 feet below the crown. Two concrete cutoff walls. Pumps in concrete pumping plant on the landside (LS). Timber steps on the LS slope. Two service poles and anchors on the LS shoulder. Electrical control gates in a metal and concrete building on the waterside (WS) shoulder. Flap gates on the WS end. Installed by USACE in 1950. (Construction of a four compartment concrete gravity outlet conduit under the levee authorized under Permit No. 1284, 1948 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 1993. USACE Sacramento O&M Manual 129, June 1954, (Station 1227+00)]. FS Date: 1/21/2014					

LM Start	1.92	Rating **	A/W	Issue No.	41 (cont)
LM End	1.92	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2020_28884_53089.jpg



WS view: CM shed for slide gate on levee shoulder (top) and outfall structure at levee toe (bottom).

Photo 2 of 3 : UCIP_SP_2020_28884_53088.jpg



WS view: motorized slide gates in CM shed on levee shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.92	Rating **	A/W	Issue No.	41 (cont)
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.783904 °	38.783904 °	
			-121.655149 °	-121.655149 °	
DWR ID	20028				

Photo 3 of 3 : UCIP_SP_2020_28884_53099.jpg



LS view: pump house at the end of levee berm.

LM Start	1.92	Rating **	A/W	Issue No.	42
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.783924 °	38.783924 °	
			-121.655140 °	-121.655140 °	
DWR ID	20029				

Comment Code

Inspector Comment

DS_ID:20029
 FS_ID:28885
 EP_NO: N/A
 Repair Type: No Action Needed
 Crossing Status: Found
 UCIP Comments: Pumping plant was working during the field visit. Hydraulic gates on outfall structure. Motorized slide gates on waterside shoulder.
 FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 3] 4 of 4: 72-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 35 feet below the crown. Two concrete cutoff walls. Pumps in concrete pumping plant on the landside (LS). Timber steps on the LS slope. Two service poles and anchors on the LS shoulder. Electrical control gates in a metal and concrete building on the waterside (WS) shoulder. Flap gates on the WS end. Installed by USACE in 1950. (Construction of a four compartment concrete gravity outlet conduit under the levee authorized under Permit No. 1284, 1948 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 1993. USACE Sacramento O&M Manual 129, June 1954, (Station 1227+00)].
 FS Date: 1/21/2014

Photo 1 of 3 : UCIP_SP_2020_28885_53095.jpg



WS view: CM shed for slide gate on levee shoulder (top) and outfall structure at levee toe (bottom).

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	--------------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.92	Rating **	A/W	Issue No.	42 (cont)
LM End	1.92	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.783924 °	38.783924 °	
			-121.655140 °	-121.655140 °	
DWR ID	20029				

Photo 2 of 3 : UCIP_SP_2020_28885_53094.jpg



WS view: motorized slide gates in CM shed on levee shoulder.

LM Start	1.92	Rating **	A/W	Issue No.	42 (cont)
LM End	1.92	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2020_28885_53093.jpg



LS view: pump house at the end of levee berm.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

Reclamation District No. 1500 Sutter Basin

WS view: concrete surge structure on waterside shoulder.

Page 8 of 22

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.93	Rating **	A/W	Issue No.	44 (cont)
LM End	1.93	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.784111 °	38.784111 °	
			-121.655067 °	-121.655067 °	
DWR ID	20025				

Photo 2 of 3 : UCIP_SP_2020_28955_53263.jpg



WS view: concrete surge structure on waterside shoulder.

LM Start	1.93	Rating **	A/W	Issue No.	44 (cont)
LM End	1.93	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2020_28955_53264.jpg



WS view: USED Bench Mark on concrete structure at levee shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.93	Rating **	A/W	Issue No.	45 (cont)
LM End	1.93	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.784127 °	38.784127 °	
			-121.655057 °	-121.655057 °	
DWR ID	20026				

Photo 3 of 3 : UCIP_SP_2020_28956_53267.jpg



WS view: USED Bench Mark on concrete structure at levee shoulder.

LM Start	1.98	Rating **	A/W	Issue No.	46
LM End	1.98	Issue Type +	Ma	Location *	
Category	Supplemental		GPS Latitude/Longitude		
			Start	End	
Item	DWR UCIP LMA Responsibility		38.784783 °	38.784783 °	
			-121.654791 °	-121.654791 °	
DWR ID	20088				

Photo 1 of 3 : UCIP_SP_2020_28891_53137.jpg



WS view: slide gate in concrete box on levee shoulder.

Comment Code

Inspector Comment

DS_ID:20088
 FS_ID:28891
 EP_NO: 10088
 Repair Type: No Action Needed
 Crossing Status: Found
 UCIP Comments: Pumping plant was working during the field visit. Three 8.5 ft. X 8.5 ft. concrete box on waterside shoulder.
 FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 1] 1 of 3: 84-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 24 feet below the crown. Pumps in concrete pumping plant on the landside (LS). Slide gates mounted on a concrete structure on the waterside (WS) slope. Discharges in a concrete spillway and the borrow pit. Ramp on the WS slope. (84-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee and all other appurtenances retained under Automatic Board Order (ABO) issued as Permit No. 10088, 1974 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 129, June 1954, (Station 1224+75), three 78-inch concrete conduits referenced].
 FS Date: 1/21/2014

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**


Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.98	Rating **	A/W	Issue No.	46 (cont)
LM End	1.98	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.784783 °	38.784783 °
				-121.654791 °	-121.654791 °
DWR ID	20088				

Photo 2 of 3 : UCIP_SP_2020_28891_53136.jpg



WS view: inside view of concrete box on levee shoulder.

LM Start	1.98	Rating **	A/W	Issue No.	46 (cont)
LM End	1.98	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2020_28891_53135.jpg



WS view: outfall structure on levee toe and concrete box on levee shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.98	Rating **	A/W	Issue No.	47
LM End	1.98	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.784818 °	38.784818 °
				-121.654778 °	-121.654778 °
DWR ID	20092				
Comment Code					
Inspector Comment					
DS_ID:20092 FS_ID:28892 EP_NO: 10088 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: Pumping plant was working during the field visit. Three 8.5 ft. X 8.5 ft. concrete box on waterside shoulder. FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 1] 2 of 3: 84-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 24 feet below the crown. Pumps in concrete pumping plant on the landside (LS). Slide gates mounted on a concrete structure on the waterside (WS) slope. Discharges in a concrete spillway and the borrow pit. Ramp on the WS slope. (84-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee and all other appurtenances retained under Automatic Board Order (ABO) issued as Permit No. 10088, 1974 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 129, June 1954, (Station 1224+75), three 78-inch concrete conduits referenced]. FS Date: 1/21/2014					

LM Start	1.98	Rating **	A/W	Issue No.	47 (cont)
LM End	1.98	Issue Type +	Ma	Location *	

Photo 1 of 3 : UCIP_SP_2020_28892_53147.jpg



WS view: outfall structure on levee toe and concrete box on levee shoulder.

Photo 2 of 3 : UCIP_SP_2020_28892_53146.jpg



WS view: slide gate in concrete box on levee shoulder.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.98	Rating **	A/W	Issue No.	47 (cont)
LM End	1.98	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.784818 °	38.784818 °
				-121.654778 °	-121.654778 °
DWR ID	20092				

Photo 3 of 3 : UCIP_SP_2020_28892_53145.jpg



WS view: inside view of concrete box on levee shoulder.

LM Start	1.99	Rating **	A/W	Issue No.	48
LM End	1.99	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.784856 °	38.784856 °
				-121.654762 °	-121.654762 °
DWR ID	20093				

Photo 1 of 3 : UCIP_SP_2020_28893_53157.jpg



WS view: slide gate in concrete box on levee shoulder.

Comment Code					
Inspector Comment					
DS_ID:20093 FS_ID:28893 EP_NO: 10088 Repair Type: No Action Needed Crossing Status: Found UCIP Comments: Pumping plant was working during the field visit. Three 8.5 ft. X 8.5 ft. concrete box on waterside shoulder. FIELD_STRUCT_DESC: [Reclamation District No. 1500, Pumping Plant No. 1] 3 of 3: 84-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee, 24 feet below the crown. Pumps in concrete pumping plant on the landside (LS). Slide gates mounted on a concrete structure on the waterside (WS) slope. Discharges in a concrete spillway and the borrow pit. Ramp on the WS slope. (84-inch by 84-inch reinforced concrete box drainage discharge conduit under the levee and all other appurtenances retained under Automatic Board Order (ABO) issued as Permit No. 10088, 1974 - Reclamation District No. 1500). [Additional Reference(s): DWR Levee Log, 2005. USACE Sacramento O&M Manual 129, June 1954, (Station 1224+75), three 78-inch concrete conduits referenced]. FS Date: 1/21/2014					

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	1.99	Rating **	A/W	Issue No.	48 (cont)
LM End	1.99	Issue Type +	Ma	Location *	
Category	Supplemental			GPS Latitude/Longitude	
				Start	End
Item	DWR UCIP LMA Responsibility			38.784856 °	38.784856 °
				-121.654762 °	-121.654762 °
DWR ID	20093				

Photo 2 of 3 : UCIP_SP_2020_28893_53156.jpg



WS view: inside view of concrete box on levee shoulder.

LM Start	1.99	Rating **	A/W	Issue No.	48 (cont)
LM End	1.99	Issue Type +	Ma	Location *	

Photo 3 of 3 : UCIP_SP_2020_28893_53155.jpg



WS view: outfall structure on levee toe and concrete box on levee shoulder.

LM Start	2.77	Rating **	M	Issue No.	23
LM End	4.55	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.796046 °	38.820909 °
				-121.654848 °	-121.663630 °
DWR ID	DWR_RD1500_02_s_2020_23				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location
LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

** Rating
A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type
Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	2.77	Rating **	M	Issue No.	24
LM End	4.55	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.796046 °	38.820910 °	
			-121.654848 °	-121.663630 °	
DWR ID	DWR_RD1500_02_s _ 2020_24				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	4.62	Rating **	M	Issue No.	25
LM End	9.52	Issue Type +	Ma	Location *	LS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.821976 °	38.888607 °	
			-121.663692 °	-121.635952 °	
DWR ID	DWR_RD1500_02_s _ 2020_25				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	4.62	Rating **	M	Issue No.	26
LM End	9.83	Issue Type +	Ma	Location *	WS
Category	Earthen Levee		GPS Latitude/Longitude		
			Start	End	
Item	Vegetation		38.821977 °	38.893138 °	
			-121.663691 °	-121.636644 °	
DWR ID	DWR_RD1500_02_s _ 2020_26				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	8.31	Rating **	A/W	Issue No.	20
LM End	8.31	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Animal Control			38.872391 °	38.872391 °
				-121.642262 °	-121.642262 °
DWR ID	DWR_RD1500_02_f_2019_20				
Comment Code					
A3 : No rodents visible, but rodent burrows visible; need to backfill and compact or grout burrows.					
Inspector Comment					
Rodent hole on the landside slope. Recommend monitoring.					

Photo 1 of 1 : SP_2020_RD1500_190_20_20200228_00010.jpg



View of rodent hole on the landside slope. Fall 2019.

LM Start	9.55	Rating **	M	Issue No.	27
LM End	9.83	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.889155 °	38.893091 °
				-121.636024 °	-121.636636 °
DWR ID	DWR_RD1500_02_s_2020_27				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	10.74	Rating **	M	Issue No.	28
LM End	11.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.906139 °	38.913539 °
				-121.638891 °	-121.640171 °
DWR ID	DWR_RD1500_02_s_2020_28				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	10.74	Rating **	M	Issue No.	29
LM End	11.25	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.906139 °	38.913539 °
				-121.638891 °	-121.640171 °
DWR ID	DWR_RD1500_02_s_2020_29				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	14.13	Rating **	U	Issue No.	4
LM End	14.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			38.947628 °	38.947628 °
				-121.669764 °	-121.669764 °
DWR ID	DWR_RD1500_02_s_2012_4				
Comment Code					
Inspector Comment					
The concrete pad and the PVC underneath are broken apparently by an attempt to pull out the head of the well.					

Photo 1 of 3 : SP_2020_RD1500_190_4_20200228_00001.jpg



View of underseepage relief well with destroyed concrete pad as well as PVC pipes. Fall 2016.

LM Start	14.13	Rating **	U	Issue No.	4 (cont)
LM End	14.13	Issue Type +	Ma	Location *	LS

Photo 2 of 3 : SP_2020_RD1500_190_4_20200228_00002.jpg



Another view of damaged well. Fall 2016.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------	--

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	14.13	Rating **	U	Issue No.	4 (cont)
LM End	14.13	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			38.947628 °	38.947628 °
				-121.669764 °	-121.669764 °
DWR ID	DWR_RD1500_02_s_2012_4				

Photo 3 of 3 : SP_2020_RD1500_190_4_20200228_00003.jpg



View of the relief well at historical boil 12. Fall 2015.

LM Start	14.47	Rating **	A/W	Issue No.	11
LM End	14.47	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			38.951413 °	38.951413 °
				-121.673856 °	-121.673856 °
DWR ID	DWR_RD1500_02_s_2012_11				
Comment Code					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD1500_190_11_20200228_00004.jpg



A relief well at historical boil 16. Fall 2015.

LM Start	15.98	Rating **	M	Issue No.	30
LM End	16.10	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.966477 °	38.967570 °
				-121.694044 °	-121.695744 °
DWR ID	DWR_RD1500_02_s_2020_30				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	17.47	Rating **	M	Issue No.	31
LM End	17.59	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.980075 °	38.981116 °
				-121.715621 °	-121.717293 °
DWR ID	DWR_RD1500_02_s_2020_31				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	18.17	Rating **	A/W	Issue No.	13
LM End	18.17	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			38.987031 °	38.987031 °
				-121.725049 °	-121.725049 °
DWR ID	DWR_RD1500_02_s_2012_13				
Comment Code					
Inspector Comment					

Photo 1 of 2 : SP_2020_RD1500_190_13_20200228_00006.jpg



View of two of four drains on the landward side of the levee. Fall 2015.

LM Start	18.17	Rating **	A/W	Issue No.	13 (cont)
LM End	18.17	Issue Type +	Ma	Location *	LS

Photo 2 of 2 : SP_2020_RD1500_190_13_20200228_00007.jpg



View of the 4 drains at the levee toe on the landward side. Fall 2015.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable N : Not Inspected/Rated M : Minimally Acceptable C : Corrected U : Unacceptable A/W : Acceptable but Monitor & Maintain		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	--	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------	--	-------------------------------------------------------------------------------------------------------------

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Spring 2020

Reclamation District No. 1500 Sutter Basin

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 02 Sutter Bypass	Right	20.72	03/18/2020 03/18/2020	Zach Jojola

LM Start	18.43	Rating **	A/W	Issue No.	15
LM End	18.43	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Underseepage Relief Wells			38.989962 °	38.989962 °
				-121.727896 °	-121.727896 °
DWR ID	DWR_RD1500_02_s_2015_15				
Comment Code					
Inspector Comment					

Photo 1 of 1 : SP_2020_RD1500_190_15_20200228_00008.jpg



View of the toe drainage at the landward toe berm. Fall 2015.

LM Start	18.77	Rating **	M	Issue No.	32
LM End	20.71	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.994287 °	39.021231 °
				-121.731171 °	-121.741087 °
DWR ID	DWR_RD1500_02_s_2020_32				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

LM Start	18.77	Rating **	M	Issue No.	38
LM End	20.71	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			38.994289 °	39.021234 °
				-121.731172 °	-121.741093 °
DWR ID	DWR_RD1500_02_s_2020_38				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
----------------------------------------------------------------------------------------------	------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------	-------------------------------------------------------------------------------------------------------------